
Military Affairs

1. St. Cloud Readiness Center: wall repairs needed









1. St. Cloud Readiness Center: water leaks and ceiling replacement







2. Wadena Readiness Center: roof repair




2. Wadena Readiness Center: roof repair



2. Wadena Readiness Center: renovate inadequate facilities




2. Wadena Readiness Center: update for code compliance (power strip connecting)



4. Grand Rapids Readiness Center: electrical system upgrade needed







5. Rosemount Readiness Center: water damage



5. Rosemount Readiness Center: water damage



5. Rosemount Readiness Center: water damage



6. Fergus Falls Readiness Center: boiler controller outdated



6. Fergus Falls Readiness Center: renovate inadequate facilities

